INSTALLATION & OPERATION MANUAL

SP711-3 REV. A 3-Wire Analog Transmitter

DOC#: MN-711-3-A.doc



Precision Industrial Flow Measuring Devices and Controls

2363 Sandifer Boulevard, Westminster, South Carolina 29693 USA Voice: (864) 647-2065 FAX: (864) 647-1255 1-800-258-1165 www.sponsler.com

SPECIFICATIONS

Temperature:	Operating -40 to 85°C Storage -65 to 125°C
Input Voltage:	12-28VDC 50mA min. Protected against polarity reversal
Signal Input:	Frequency 0-10KHz Amplitude 20mV - 35V sine or square wave Sensitivity field adjustable Impedance 10K
Analog Output	0V @ 0Hz, 5 or 10V @ desired full scale frequency Full scale range - 75Hz-10KHz selectable Consult factory for other ranges Response time - 95% of change in 1 second Linearity3% F/S Tempco - < 2% of reading over entire temperature range Minimum load resistance 250 ohms
Features:	Switch selectable output range Mounts directly on flowmeter
Enclosure:	FM Approved, CSA Certified Class I Groups B, C, D Class II Groups E, F, G Weight 1.7 lbs.

The SP711-3 is a meter mounted 3-wire analog transmitter designed to linearly convert a frequency input to an equivalent voltage output whose level is switch selectable @ 0-5V/0-10V. When incorporated with a turbine flowmeter a voltage representation proportional to flow is obtainable.

A full-scale frequency range of 75Hz – 10KHz is jumper selectable. The span adjustment establishes the frequency point at which the full-scale voltage output (5V or 10V) is achieved. The sensitivity adjustment permits the SP711-3 to discriminate between a signal input or noise by increasing (CCW) or decreasing (CW) the input signal amplitude necessary to be processed as a valid signal. This in conjunction with direct meter mounting allows the SP711-3 to operate effectively in noisy environments.

BENCH TEST CALIBRATION PROCEDURE

Required Equipment: Power Supply 12-28VDC, Digital Multimeter (DMM), Frequency Generator, & Frequency Counter

Refer to Figure

Test Procedure:

- A) Connect DMM positive & negative leads to J1-3,4 respectively & set DMM function to DC Volts
- B) Connect power supply positive & negative leads to J1-5,4 respectively
- **C)** Connect frequency generator positive & negative leads to J1-1,2; respectively. Set output to sinewave & amplitude to zero
- D) Install jumper @ JU2-4 for desired full-scale frequency range, set S1 to 0-5V or 0-10V for desired output level.
- E) Set 'Sensitivity' adjust (R1) fully clockwise
- F) Turn power supply & frequency Generator 'ON', DMM should indicate 0VDC
- G) Adjust 'ZERO' (R10) for DMM indication of .000V
- **H)** Adjust signal amplitude of frequency generator to 20mV & frequency to maximum desired point (full scale frequency)
- I) Adjust 'SPAN' (R8) for 5.00V or 10.00V DMM indication
- J) Reduce signal amplitude of frequency generator to zero, adjust 'ZERO' (R10) for DMM indication of .000V if necessary
- K) Adjust signal amplitude of frequency generator to 20mV, adjust 'SPAN' (R8) for 5.00V or 10.00V DMM indication if necessary
- L) Adjust frequency of frequency generator to exactly 50% of maximum frequency point in step H, DMM should indicate 2.50V or 5.00V <u>+</u> .02V.

To check linearity @ any frequency point, incorporate the following formula:

 $(F/F_{max} X \text{ full scale output}) = Volts$

Ex. Assume maximum frequency point = 2000Hz & full scale output

Voltage = 10VCheck for linearity @ 750Hz point 750/2000 = .375 10 X .375 = 3.75 DMM should indicate 3.75V + .03V

